

Armory (0006)

Classroom Repairs Phase 2

Building Information

Year Built: 1914

Project Area Primary Users: General Assign.

Affected Rooms: 328-331, 333, 429-433

Room Capacities: 40-70 seats

Proposed Project Budget: \$350,000 est

Classroom Renov. Pool Funding \$230,000

Proposed IT source: \$TBD

Narrative

This project is the second phase of classroom repairs and upgrades in the Armory. This project will address the west classrooms and hallways on the third and fourth floors.

The Armory is a high student use facility as well as a campus landmark, and its West classrooms are heavily used for general assignment courses. Yet, many of these classrooms are in very poor condition and in need of repairs. Some, but not all, have received classroom IT upgrades.

The project will **replace aged & deteriorated vinyl asbestos tile** in all **classrooms** and associated hallways, as well as **repair and repaint walls**. **Classroom IT systems** and **new seating** will be provided in rooms that do not yet have sufficient equipment or furnishings.




Existing Conditions

Left Above
Room 331
Wall damage



Right Above
Room 328
Poor wall finish conditions



Left Below
Room 429
Damaged flooring

Right Below
Room 429
Aged & damaged seating

