

Loomis Laboratory (0067)

Infrastructure Repairs

Building Information

Year Built: 1959

Project Area Primary Users: Students

Affected Rooms: 136, 137, 139, 141, 143, 147, 151, 158

Room Capacities: 136: 55 seats, 137: 29 seats, 141: 303 seats 143: 29 seats, 147: 27 seats, 151:202 seats, 158: 55 seats

Narrative

This project required a feasibility study to further define the scope and budget. The **instructional spaces** of Loomis Lab were improved significantly. The rooms had **inadequate HVAC, antiquated ceilings and lights** as well as **deteriorated flooring**. **IT was installed in classrooms not already equipped.** This project provided **fire suppression** and other **life safety components**. **Instructional space and surrounding service areas were revitalized.** **Programmatic departmental space was also renovated with the addition of campus unit funds.**



Existing Conditions

After

Room 158 - Right Above
Renovated instructional space



Room 144 - Below
Renovated instructional space

Hallway - Right Below
Updated wall finishes/flooring



Before

Room 209 - Left
Deteriorated flooring



Room 209 - Center
Dirty ceilings resulting from the air diffuser



Room 209 - Right
Portions of floor missing

